

UNBOXING



Hoist the heater out of the box.

SET UP



2

CONNECT TO THE POWER MAINS



Alternatively connect wiring as follows:

Phase	Brown
Phase	Black or Grey
Ground	🖊 Green/Yellow

TURN ON THE HEATER





Black (USA)Black (USA)

Turn main switch from 0 to 1. You'll hear a short beep and the display turns on.



Maintenance & Reliability Equipment maintenance made - easier + faster + safer e: info@mrequip.com.au m: +61 417 954 430 w: mrequip.com.au



SURETHERM 30

THE WORKPIECE



POSITIONING THE WORKPIECE






Place the workpiece in a horizontal or vertical position.



CHOOSING THE RIGHT YOKE






Use largest yoke available or stack two yokes to center the workpiece around the yoke.



USING THE TEMPERATURE PROBE



Plug in with the red dot facing upwards



When using a single probe, place the probe on the workpiece near the bore.



Maintenance & Reliability Equipment maintenance made - easier + faster + safer e: info@mrequip.com.au m: +61 417 954 430 w: mrequip.com.au